

Tiguan wet rear floor and spare-tire well

FIX-006 / REV A / 2026.09.01

Trace water from the highest fresh wet point and isolate one source at a time.

STATUS	Recovered/Partial
CLASSIFICATION	FIX
MATERIAL	TROUBLESHOOTING
DISPOSITION	PUBLIC / RECOVERED/PARTIAL
CATEGORY	Repairs / Technology
RECORD TYPE	troubleshooting

GOAL

Run the first test described in this guide and record the result for tiguan wet rear floor and spare-tire well.

SOURCE STATE

New reference guidance; not a recovered test result

EQUIPMENT

- Basic inspection tools
- Service information for the exact model
- Notebook or photo record

METHOD / STEPS

1. Remove loose cargo and document wet areas after rain or washing; inspect under the cargo floor without disturbing wiring.
2. Dry accessible surfaces, then test one region at a time with gentle water: roof/drain area, hatch perimeter, lamps or other suspected openings.
3. Check whether water tracks from above, runs along trim or pools from a lower seam.
4. Repair the confirmed path and dry padding as well as carpet; inspect nearby electrical connectors if they were wetted.

THINGS TO WATCH FOR

The lowest puddle is often not the entry point. Do not reseal every seam blindly or block designed drains. Saturated foam can remain wet after the carpet feels dry.

FIRST TEST / WHAT TO RECORD

A repeated isolated water test stays dry and moisture does not return beneath the padding.

RESULT / WHERE THIS STANDS

A repeated isolated water test stays dry and moisture does not return beneath the padding.

TROUBLESHOOTING

- The lowest puddle is often not the entry point. Do not reseal every seam blindly or block designed drains. Saturated foam can remain wet after the carpet feels dry.

SAFETY / LIMITATIONS

- Use qualified judgment and current manufacturer or code guidance for safety-critical work.

SPECIFICATION

TYPE	Troubleshooting
SUBJECT	Tiguan wet rear floor and spare-tire well
VALIDATION	Observed symptom / tested cause / result

DEVELOPMENT HISTORY

2026.09.01 / Rev A

Imported as an independent manifest record; public copy keeps uncertainty visible.

REFERENCE NOTES

Volkswagen owner reference
(<https://www.vw.com/en/owners-and-services/about-my-vehicle/owners-manuals.html>).

HOW-TO SOURCES

Volkswagen owner reference
<https://www.vw.com/en/owners-and-services/about-my-vehicle/owners-manuals.html>

RELEASED MATERIAL / SOURCE LINKS

fix-006-public-summary.txt

PUBLIC SUMMARY / RECOVERED NOTES

<https://u225x.com/downloads/manifest-records/fix-006-public-summary.txt>

RETURN TO THE LIVING RECORD

Tiguan wet rear floor and spare-tire well

This PDF preserves the public notes at this revision. Visit the record for updates and attached images.

<https://u225x.com/record/FIX-006>