

# Tiguan HVAC Programming Issue

CHAT-0373 / REV EXPORT-03 / 2026.07.15

A conversation-specific public summary of tiguan hvac programming issue, distilled from the supplied export. The detailed excerpts remain available in the released note file.

|                |                                         |
|----------------|-----------------------------------------|
| STATUS         | RECOVERED / SPECIFIC NOTE               |
| CLASSIFICATION | ERR                                     |
| MATERIAL       | CHAT EXPORT / VEHICLE NOTES             |
| DISPOSITION    | PUBLIC CONVERSATION EXCERPTS / REDACTED |
| CATEGORY       | Vehicle Notes                           |
| RECORD TYPE    | repair-thread                           |

## TECHNICAL NOTES

Conversation-specific knowledge extracted from the tiguan hvac programming issue discussion.

## CONVERSATION / QUESTION AND CONTEXT

What part did we think needed programmed on the tiguan

## CONVERSATION / EXTRACTED GUIDANCE

1. The 10A fuse only blew when the A/C was turned on.
2. When you unplugged the climate control module, the fuse stopped blowing.
3. The A/C compressor had already been tested and was reportedly good.
4. We also talked about the Tiguan having had a reverse polarity incident in the past, which can damage or corrupt electronic modules.
5. Replace the HVAC/climate control module if it's faulty.
6. Have it coded/programmed to the vehicle with VW diagnostic software (typically ODIS at a dealer or a VW-capable independent shop with tools like ODIS or certain advanced scan tools).
7. The wiring from the climate module to the A/C compressor.
8. The A/C compressor control valve (if equipped).

---

## SPECIFICATION

|               |                                  |
|---------------|----------------------------------|
| SOURCE        | Supplied ChatGPT export          |
| CATEGORY      | Vehicle Notes                    |
| CONVERSATION  | 2 user turns / 2 assistant turns |
| ATTACHMENTS   | 2 references detected            |
| PUBLIC DETAIL | Extracted knowledge + excerpts   |

---

## DEVELOPMENT HISTORY

2026.07.15 / EXPORT-04

Matched to the supplied export; key guidance is surfaced separately and the raw transcript remains unpublished.

---

## RELEASED MATERIAL / SOURCE LINKS

CHAT-0373-public-note.txt

PUBLIC-SAFE CONVERSATION NOTE / UNIQUE FILE

<https://u225x.com/downloads/chat-records/CHAT-0373-public-note.txt>

---

## RETURN TO THE LIVING RECORD

Tiguan HVAC Programming Issue

This PDF preserves the public notes at this revision. Visit the record for updates and attached images.

<https://u225x.com/record/CHAT-0373>

---