

Tiguan sunroof-drain clearing

FIX-005 / REV A / 2026.09.01

Confirm drainage gently without dislodging hidden hoses or flooding the cabin.

STATUS	Recovered/Partial
CLASSIFICATION	FIX
MATERIAL	TROUBLESHOOTING
DISPOSITION	PUBLIC / RECOVERED/PARTIAL
CATEGORY	Repairs / Technology
RECORD TYPE	troubleshooting

GOAL

Run the first test described in this guide and record the result for tiguan sunroof-drain clearing.

SOURCE STATE

New reference guidance; not a recovered test result

EQUIPMENT

- Basic inspection tools
- Service information for the exact model
- Notebook or photo record

METHOD / STEPS

1. Park level, remove loose debris from the visible sunroof channel and identify the drains using the exact-year service information.
2. Introduce a small controlled amount of water to one drain at a time while another person watches the expected outlet and cabin.
3. If flow is restricted, use only the manufacturer-approved cleaning method with a soft suitable tool and stop at resistance.
4. Repeat the small water test and dry any affected interior material completely.

THINGS TO WATCH FOR

High-pressure air, hard wire or excessive force can detach or puncture a drain hose. A clear opening does not prove the full hose is connected. Persistent leakage may be a disconnected hose or seal issue.

FIRST TEST / WHAT TO RECORD

Water exits at the intended outlet without appearing inside, and the result holds on a later controlled check.

RESULT / WHERE THIS STANDS

Water exits at the intended outlet without appearing inside, and the result holds on a later controlled check.

TROUBLESHOOTING

- High-pressure air, hard wire or excessive force can detach or puncture a drain hose. A clear opening does not prove the full hose is connected. Persistent leakage may be a disconnected hose or seal issue.

SAFETY / LIMITATIONS

- Use qualified judgment and current manufacturer or code guidance for safety-critical work.

SPECIFICATION

TYPE	Troubleshooting
SUBJECT	Tiguan sunroof-drain clearing
VALIDATION	Observed symptom / tested cause / result

DEVELOPMENT HISTORY

2026.09.01 / Rev A

Imported as an independent manifest record; public copy keeps uncertainty visible.

REFERENCE NOTES

Volkswagen owner reference
(<https://www.vw.com/en/owners-and-services/about-my-vehicle/owners-manuals.html>).

HOW-TO SOURCES

Volkswagen owner reference
<https://www.vw.com/en/owners-and-services/about-my-vehicle/owners-manuals.html>

RELEASED MATERIAL / SOURCE LINKS

fix-005-public-summary.txt

PUBLIC SUMMARY / RECOVERED NOTES

<https://u225x.com/downloads/manifest-records/fix-005-public-summary.txt>

RETURN TO THE LIVING RECORD

Tiguan sunroof-drain clearing

This PDF preserves the public notes at this revision. Visit the record for updates and attached images.

<https://u225x.com/record/FIX-005>