

Logo Gear / Moving-Part Print Notes

DAT-0027 / REV A / 2026.09.01

The recovered result was strong enough to move but slightly loose, with small lettering and minor first-layer stringing still needing attention. The next revision is structured around clearance, compensation, shell, top-surface, seam, and first-layer records rather than guessed settings.

STATUS	UNDER TEST
CLASSIFICATION	DAT
MATERIAL	3D PRINT / MOVING PART
DISPOSITION	OBSERVED / RETEST NEEDED

TECHNICAL NOTES

A moving-part study balancing strength, free motion, lettering quality, and first-layer behavior.

QUICK SETTINGS FROM THE RECORD

GOAL	Strong and freely moving.
OBSERVED	Slightly loose / minor stringing.
NEXT	Clearance / compensation / surface records.
STATUS	Retest needed.

SPECIFICATION

GOAL	Strong and free-moving
PRINTER	Creator 5 Pro
OBSERVED	Slightly loose / stringing
NEXT	Record finished clearance

DEVELOPMENT HISTORY

2026.09.01 / Rev A

Added the moving-part observations and the complete next-revision checklist.

RELEASED MATERIAL / SOURCE LINKS

DAT-0027_logo-gear-notes.txt

NOTES / 2 KB

https://u225x.com/downloads/DAT-0027_logo-gear-notes.txt

CONNECTED RECORDS

OBJ-0042

<https://u225x.com/record/OBJ-0042>

DAT-0028

<https://u225x.com/record/DAT-0028>

RETURN TO THE LIVING RECORD

Logo Gear / Moving-Part Print Notes

This PDF preserves the public notes at this revision. Visit the record for updates and attached images.

<https://u225x.com/record/DAT-0027>